

Link do produktu: <https://roltruck.pl/czujnik-temperatury-silnika-deutz-m10-p-19398.html>

CZUJNIK TEMPERATURY SILNIKA DEUTZ M10

Cena brutto	47,26 zł
Cena netto	38,42 zł
Dostępność	Dostępny
Czas wysyłki	24 godziny
Numer katalogowy	02405960

Opis produktu

Czujnik temperatury silnika Deutz Fahr 02405960

Pasuje do :

DEUTZ FAHR:

06: 10006, 10006F, 10006U, 13006, 16006, 2506, 3006, 3006F, 4006, 4006F/S, 4006U, 4506, 4506F, 4506US, 5006, 5006F, 5006U, 5206, 5206F, 5206U, 5506, 5506F, 5506U, 6006, 6006F, 6006U, 6206, 6206F, 6206U, 6806, 6806F, 6806U, 7006, 7006F, 7006U, 7206, 7206A, 7206F, 7206U, 7506, 7506F, 7506U, 8006, 8006F, 8006U, 9006, 9006A, 9006F, 9006U

07: 2807, 3607, 3607F, 4007, 4007F, 4007U, 4507, 4507A, 4507F, 4807, 4807A, 4807F, 5207, 5207A, 5207F, 6007, 6007A, 6007F, 6207, 6207A, 6207F, 6507, 6507A, 6507F, 6807, 6807A, 6907, 7007, 7007A, 7207, 7207A, 7807, 7807A

Agroprima: Agroprima 4.31, Agroprima 4.56, Agroprima 6.06, Agroprima 6.16

Agroxtra: Agroxtra 3.57, Agroxtra 4.07, Agroxtra 4.17, Agroxtra 4.47, Agroxtra 4.57, Agroxtra 6.07, Agroxtra 6.17

C: 4507C, 4807C, 5207C, 6007C, 6207C, 6507C, 6807C, 6907C, 7007C, 7207C, 7807C

DX: DX110, DX110A, DX120, DX120A, DX140, DX140A, DX145, DX145A, DX160, DX160A, DX85, DX85A, DX90, DX90A

DX3 SC: DX3.10SC, DX3.30SC, DX3.50SC, DX3.60SC, DX3.65SC, DX3.70SC, DX3.80SC, DX3.90SC

DX3 V/F/S: DX3.10V, DX3.30V/F, DX3.50S, DX3.50V/F, DX3.70V/F, DX3.90F, DX3.90S

DX3 VC: DX3.10VC, DX3.30VC, DX3.50VC, DX3.60VC, DX3.65VC, DX3.70VC, DX3.90VC

DX4: DX4.11

nr.porównawcze : 01173469, 01182838, 02130498, 1173469, 1182838, 213 0498,
2130498, D1173469, K1173469