

Link do produktu: <https://roltruck.pl/swieca-plomieniowa-fendt-deutz-12v-p-16286.html>



ŚWIECA PŁOMIENIOWA FENDT DEUTZ 12V

Cena brutto	90,00 zł
Cena netto	73,17 zł
Dostępność	Dostępny
Czas wysyłki	24 godziny
Numer katalogowy	11720548 ŚWIECA

Opis produktu

Świeca płomieniowa 11720548
9,5 V, 20 A,
gwint M20 x 1,5
Pasuje do :
Fendt
Agrobil S821,
200S, 200SA, 200V, 200VA, 201S, 201SA, 203P, 203P/II, 203PA, 203PA/II, 203V, 203V/II, 203VA, 203VA/II, 204P, 204PA, 204V,
204VA, 205P, 205PA, 240S, 250K, 250KA, 250LE, 250S, 250SA, 250V, 250VA, 260P, 260PA, 260S, 260SA, 260V, 260VA, 270P,
270PA, 270V, 270VA, 275SA, 275V, 275VA, 280P, 280PA,
307C, 308C, 309C,
711, 712, 714, 716,
F255GT Kommunal, F275GT Kommunal, F275GTII Kommunal, F275GTII Kommunal, FL345, FL360, FL365, FL380,
FLA380,
F255GT, F275GT, F275GTII, F345GT, F345GTM, F360GTF, F360GTH, F370GT, F370GTA, F380GHA, F380GT, F380GTA,
F380GTH, F390GTA, F395GHA, F395GTA,
Same
Typ: Frutteto 70, Frutteto 75, Galaxi 170, Hercules 170, Jaguar 100, Jaguar 95, Laser 90, Laser 150, Leopard 85, Mercury 85,
Minitauro 60, Panther 90, Panther 95, Saturno 80, Sirenetta, Solar 50, Solar 60, Taurus 60, Taurus C, Tiger 100, Tiger SIX 105,
Trident 130, Motor Same 105.2, Motor Same 105.3, Motor Same 105.4, Aurora 45, Buffalo 120, Buffalo 130, Centauro 70,
Centurion 75, Condor 55, Corsaro 70, Delfino 35, Drago 120, Explorer 60, Explorer 70, Explorer 80, Explorer 90, Falcon, Falcon
50, Falcon 55, Falcon 60, Falcon C, Frutteto 60
Typ ciągnika: 105 2 LP, 3 P, 4 P, Aurora 45, Buffalo 120, 130, Centauro 70, Exp./Special, Centurion 75, 75 Exp./Special, Condor
55, Corsaro Frutteto 70, Corsaro Synchro 70, Delfino 35, Drago 120, Explorer 60 Exp./Special, Explorer 70 Exp./Special,
Explorer 80 Exp./Special, Explorer 90 Exp./Special Turbo, Falcon, Frutteto 60, 75, Galaxy 170, Hercules 170, Jaguar 95, 100,
Laser 90, 150, Leopard 85, Export, 90 Turbo, Mercury, Minitauro 60, Panther 90, 95, Saturno Synchro 80, Sirenetta, Solar 50,
60, Taurus 60, Taurus C, Tiger 100, Six 105, Tiger Six 105, Trident 130
Deutz
10006, 10006F, 10006U, 13006, 16006, 2506, 3006, 3006F, 4006, 4006F/S, 4006U, 4506, 4506F, 4506US, 5006, 5006F,
5006U, 5206, 5206F, 5206U, 5506, 5506F, 5506U, 6006, 6006F, 6006U, 6206, 6206F, 6206U, 6806, 6806F, 6806U, 7006,
7006F, 7006U, 7206, 7206A, 7206F, 7206U, 7506, 7506F, 7506U, 8006, 8006F, 8006U, 9006, 9006A, 9006F, 9006U,
2807, 3607, 3607F, 4007, 4007F, 4007U, 4507, 4507A, 4507C, 4507F, 4807, 4807A, 4807C, 4807F, 5207, 5207A, 5207C,
5207F, 6007, 6007A, 6007C, 6007F, 6207, 6207A, 6207C, 6207F, 6507, 6507A, 6507C, 6507F, 6807, 6807A, 6807C, 6907,
6907C, 7007, 7007A, 7007C, 7207, 7207A, 7207C, 7807, 7807A, 7807C,
Agrocompact 3.30V/F, Agrocompact 3.50S, Agrocompact 3.50V/F, Agrocompact 3.70V/F, Agrocompact 3.90F, Agrocompact
3.90S,
Agrolux 60, Agrolux 70, Agrolux 80,
Agroplus 60, Agroplus 70, Agroplus 80,
Agroprima 4.31, Agroprima 4.36, Agroprima 6.06, Agroprima 6.16,
Agrostar 6.08, Agrostar 6.11, Agrostar 6.28,
Agroxtra 3.57, Agroxtra 4.07, Agroxtra 4.17, Agroxtra 6.07, Agroxtra 6.17,
55,
DX110, DX110A, DX120, DX120A, DX140, DX140A, DX145, DX145A, DX160, DX160A, DX230, DX230A, DX250, DX250A,
DX250V, DX3500, DX36, DX3700, DX3900, DX50, DX55, DX80, DX80A, DX85, DX85A, DX86, DX86A, DX90, DX90A, DX92,
DX92A,

DX3.10SC, DX3.30SC, DX3.50SC, DX3.60SC, DX3.65SC, DX3.70SC, DX3.80SC, DX3.90SC,
DX3.10V, DX3.30V/F, DX3.50S, DX3.50V/F, DX3.70V/F, DX3.90F, DX3.90S,
DX3.10VC, DX3.30VC, DX3.50VC, DX3.60VC, DX3.65VC, DX3.70VC, DX3.75VC, DX3.90VC,
DX4.10, DX4.30, DX4.31,
DX6.05, DX6.06, DX6.10, DX6.30,
Dxab 110, Dxab 120, Dxab 80, Dxab 85, Dxab 86, Dxab 90, Dxab 92,
Dxbis 110, Dxbis 120, Dxbis 85, Dxbis 90,
Hopfen DX4.17,
Intrac 2002, Intrac 2003, Intrac 2004, Intrac 2005, Intrac 2006, Intrac 6.30

nr.porównawcze :

F100001161134, G205200181010, X830030126000,

Typ silnika:

BF4L913 - Deutz
BF6L912 - Deutz
BF6L913 - Deutz
BL6L912 - Deutz
F2L912 - Deutz
F3L912 - Deutz
F3L913 - Deutz
F4L912 - Deutz
F4L913 - Deutz
F5L912 - Deutz
F5L913 - Deutz
F6L912 - Deutz
F6L913 - Deutz
F8L413 - Deutz